MIDMARK®

LR Vac Pak Upper Component Kit 002-0841-00

Warning
Disconnect power and shut off air and water before removing parts.

Parts Included

Y-Connector	*053-1526-00*
Compression Spring	*025-0049-05*
Carton	*107623*
Instructions	*003-1492-00*
Cable Ties (7") (Qty 4)	*102308*
Umbilical Corr.	
Tubing (1-1/4" OD x 11")	*S059-00123*
Vacuum Tubing (5/8" OD x 10 ft.)	*S059-00128*
Salvia Ejector	
Tubing (3/8" OD x 9 ft.)	*S059-00127*



DA170401i

NOTE:
Refer to the Delivery System Service and Parts manual for procedures and/or illustrations concerning the various hook-ups. Refer to Diagrams on next page.

NOTE:
Installation of this repair kit requires the permanent removal of the Hose Swivel in the Upper Assembly of the Assistant's Instrumentation.

Step 5: Disconnect the corrugated tubing and associated tubing inside the corrugated from the syringe control valves and solid collector. Remove the tubing.

Step 6: Connect all the tubing. Refer to diagrams on next page.

© Midmark Corporation 2003





© Midmark Corporation 2003