



Tools required:  
Phillips Head Screwdriver

Parts Included:  
(1) Cable Management Holder

- 1 Remove top of Cable Management Holder. Attach Cable Management Holder to bottom of worksurface using (4) screws.

- 2 Reattach top of Cable Management Holder by snapping in place.

