



Tools required:
Phillips head screwdriver or #2 Square drive bit

Parts Included:
(1) SAM-3L (Swing-A-Mouse) Assembly
(4) #10 x 1 1/4" Long Phillips Drive Pan Head Machine Screws

- I Position SAM-3 on indicated holes (See pict. A).
Attach assembly to the underside of
worksurface using the #10 x 1 1/4" screws (4).

