



Midmark Corporation
60 Vista Drive
Versailles, Ohio 45380
1-800-MIDMARK
midmark.com

Memo

Date: December 8, 2017

To: 625 Barrier Free Examination Table Installed Base

From: John Shevlin, Vice-President Quality and Regulatory

Re: Potential Choking Hazard

Midmark has identified a potential choking hazard with the bubble level and is taking proactive steps to eliminate this condition. There have been no reported incidents of choking; however, we feel it is best to offer a solution to mitigate this concern.

Should you wish, there is a service kit available and the details can be found on the Tech Service webpage found here:
http://www.midmark.com/docs/librariesprovider6/pdfs/003-10139-00.pdf?sfvrsn=37c11304_2